Operating Rod & Poppet Valve Installation Program Bendix Master-Vac Type Units


Send in your original Operating Rod or Rear Diaphragm Plate (where applicable)



Also, send back with the Operating Rod Poppet Valve – 62-300 or 62-521 Rubber Insert – 62-301*



We will remove and install your new Poppet Valve





Labor Charge

Part No. 62-1207 - \$25.00

Shipping

Customer is responsible for all shipping charges

Please Note

We will install a New Poppet Valve with Proof of Purchase of one of our Repair Kits



info@harmonclassicbrakes.com www.harmonclassicbrakes.com 6781880-9299

Important Notice

Brake fluid found in the vacuum can of any booster causes the internal parts to degrade & fail.

Master Cylinder and Brake Booster must be replaced.

MASTER-VAC POWER BRAKE UNIT

Vacuum-Suspended Tandem Diaphragm Type with Dual System Master Cylinder (SECOND DESIGN)

